

M6X16-GB70. 1-2008 六个圆柱头内六角螺钉 连接桁架Z轴 Connect the truss Z axis



Ø90

M5 Air port



	警告:
	1.当操作夹爪工作时,请人员务必远离夹爪和机器人的活动部位,否
	则将会造成人身伤害的险;
	2.由于不同物件有其不同的摩擦系数,当初次夹持工件时,请在空旷
	场地进行试夹,确保夹稳固后方可装机工作,否则将会有跌落工件
	砸伤机器或人员的风险
	Warning:
	1.When operating the gripper, please keep away from it
°C)	Gripper and robot's moving parts, otherwise it will Risk of
	personal injury;
	2. Because different objects have different friction coefficients,
4	When clamping the workpiece for the first time, please try
Bar)	clamping in an open field. Ensure that the clamping is firm
	before the machine can work, otherwise it will There is a risk
	that falling workpieces may damage machines or personnel.